

限用物質含有情況標示聲明書

Declaration of the Presence Condition of the Restricted Substances Marking

證書號碼/受理編號：CI436267062736號00
Certificate No./Application No.

商品標籤及商品檢驗標識：(Picture)
Product Label and Commodity Inspection Mark.

樣張及其標示位置：限用物質含有情況提供於 <http://www.heran.com.tw>
Sample and its location

| | | | | | | | |
|--|--|----------------|---------------|---|-------------------------------------|---|--|
| 設備名稱：窗型空氣調節機，型號（型式）：HW-GL41 | | Equipment name | | Type designation (Type) | | 系列型號：HW-GL36 | |
| 單元 Unit | 限用物質及其化學符號 Restricted substances and its chemical symbols | | | | | | |
| | 鉛Lead (Pb) | 汞Mercury (Hg) | 鎘Cadmium (Cd) | 六價鉻 Hexavalent chromium (Cr ⁺⁶) | 多溴聯苯 Polybrominated biphenyls (PBB) | 多溴二苯醚 Polybrominated diphenyl ethers (PBDE) | |
| 遙控器 | ○ | ○ | ○ | ○ | ○ | ○ | |
| 控制器元件 | ○ | ○ | ○ | ○ | ○ | ○ | |
| 電線元件 | ○ | ○ | ○ | ○ | ○ | ○ | |
| 外殼元件 | ○ | ○ | ○ | ○ | ○ | ○ | |
| 馬達元件 | ○ | ○ | ○ | ○ | ○ | ○ | |
| 電路板元件 | — | ○ | ○ | ○ | ○ | ○ | |
| <p>備考1. “超出0.1 wt %”及“超出0.01 wt %”係指限用物質之百分比含量超出百分比含量基準值。 Note 1: “Exceeding 0.1 wt %” and “exceeding 0.01 wt %” indicate that the percentage content of the restricted substance exceeds the reference percentage value of presence condition.</p> <p>備考2. “○”係指該項限用物質之百分比含量未超出百分比含量基準值。 Note 2: “○” indicates that the percentage content of the restricted substance does not exceed the percentage of reference value of presence.</p> <p>備考3. “—”係指該項限用物質為排除項目。 Note 3: The “—” indicates that the restricted substance corresponds to the exemption.</p> | | | | | | | |

茲切結保證所提供之商品限用物質含有情況標示內容係經執行測試作業或採適當之品質管理措施，並備置前述相關文件，確認正確無誤後提供貴局。並同意配合貴局執行後市場管理作業所需，依商品檢驗法第49條之規定，於限期28個工作天內提供相關證明文件以供審查。

I hereby ensure that “the presence conditions of the restricted substance” provided above have been proved by testing or appropriate quality control measures, and make sure the relevant documents provided are correct and ready. Also, I agree to cooperate with BSMI, as the Article 49 of the Commodity Inspection Act stipulates, to provide the relevant documents, if needed, for verification within 28 working days when BSMI carries out the market surveillance activities.

此致 to

財團法人台灣大電力研究試驗中心

申請人：聯碩電器股份有限公司華亞廠
Applicant

負責人：蔡金土 (簽章)
Person in charge (Signature)

中華民國 106 年 10 月 12 日
DATE (year) (month) (day)



商品標籤

Product Label

| | | |
|---|---------------------------|--------------------------|
|  | 符合國家標準 台正字第 7688 號 | HERAN R32 直流變頻窗型機 |
| 機 型 | HW-GL41 | |
| 機 能 | 冷氣 除濕 | |
| 電 源 | 單相220V/60HZ | |
| 額定能力 | 冷氣4.1kW (冷氣額定中間能力:1.85kW) | |
| 額定消耗電力 | 冷氣1242W (冷氣額定中間消耗電力:490W) | |
| 冷氣季節性能指數CSPF | 4.17(kWh/kWh) | |
| 額定運轉電流 | 冷氣5.6A | |
| 起動電流 | 冷氣5.6A | |
| 冷 媒 | R32 630g | |
| 外型尺寸 | 660W*428H*700D mm | |
| 重 量 | 50kg | |
| 製造年份 | 2017年 | |
| 製造國別 | 中華民國 | |
| 防濕防塵 | 室內IPX0 室外IPX4 | |
| 防電擊等級 | I類 | |
| 適用氣候型態 | T1 | |
| 禾聯碩股份有限公司 | 桃園市龜山區科技三路88號 | |
| TEL : 03-396-1188 | | |

RoHS限用物質含量
請參考官方網址
官方網址:www.heran.com.tw





R43700-TERTEC
RoHS 3BU03396

商品檢驗標識

Commodity Inspection Mark

份聯業
 蔡有碩
 金限電
 土公器
 司股用
 章
 商
 品
 檢
 驗



樣張標示位置

The location of sample of the marking

